

Service Centre Report

Customer Name: Sarah Johnson

Contact Number: +1-555-234-5678

Vehicle/Device Model: Honda Accord 2021

Service Request Number: SR456789

Date of Submission: 2025-02-27

Issue Reported

Description: Air conditioning not cooling properly.

Reported By: Sarah Johnson

Diagnosis & Repair Details

Diagnosis: Low refrigerant levels and faulty compressor.

Repair Performed: Refilled refrigerant and replaced compressor.

Parts Replaced: AC Compressor (1), Refrigerant Refill

Technician Name: Daniel Smith

Service Status

Status: Completed

Estimated Completion Date: 2025-02-28

Additional Notes: System tested, AC cooling restored.

Authorized Signature:

Daniel Smith

Date: 2025-02-28